

## **Product Bulletin**

Document #: PB24392X2 Issue Date: 07 Oct 2022

Title of Change:	Update for <b>PB24392X</b> - To identify specific sites affected with the change including the transition period.		
Effective date:	07 Oct 2022		
Contact information:	Contact your local onsemi Sales Office or KrisJudelo.Dayna@onsemi.com		
Type of notification:	This Product Bulletin is for notification purposes only. onsemi will proceed with implementation of this change upon publication of this Product Bulletin.		
Change Category:	Test Change		
Change Sub-Category(s):	Shipping/Packaging/Marking		
Sites Affected:			
onsemi Sites		External Foundry/Subcon Sites	
onsemi Cebu, Philippines		Greatek Electronics Inc., Taiwan	
onsemi Leshan, China		HANA Microelectronics, China	
onsemi Seremban, Malaysia		JCET, China	

## **Description and Purpose:**


This update to PB24392X is to list all of the affected sites and clarify that the transition period will be until Dec 31,2022.

SOSM and SOT223 package assembled in various listed sites will start to use onsemi Marking Layout Configuration.

This is part of the alignment and marking standardization.

For a specific OPN that is build in different sites will now have the same lay out scheme and will just differ on the plant code.

Sample marking change below.



TEM001796 Rev. D Page 1 of 2

Marking.

Some products may not follow the Generic



## **Product Bulletin**

Document #: PB24392X2 Issue Date: 07 Oct 2022

## **List of Affected Standard Parts:**

**Note**: Only the standard (off the shelf) part numbers are listed in the parts list. Any custom parts affected by this PCN are shown in the customer specific PCN addendum in the PCN email notification, or on the **PCN Customized Portal**.

2N7002	2N7002-F169	2N7002-G
BAS31	BAS35	BAV23S
BCP54	BCP55	BCV26
BCW71	BSR14	BSR16
BSR57	BSR58	BSS123
BSS123-F169	BSS123-G	BSS138-F169
BSS138-G	BSS84-H	FAN2558S10X
FAN2558S12X	FAN2558S13X	FAN2558S15X
FAN2558S18X	FAN2558S25X	FAN2558S33X
FAN2558S35X	FAN2558S38X	FAN2558SX
FAN3100CSX	FAN3100TSX	FAN3111CSX
FAN5622SX	FAN5333BSX	FAN5333ASX
FAN5331SX	FAN41501SX	FAN4146SX
FAN4146ESX	FAN3180TSX	FAN3111ESX

TEM001796 Rev. D Page 2 of 2