


Product/Process Change Notifications



PCN - 15 112-R.1

Release Date: November 02 2015

Product Name:	SAS and SATA receptacles		
	SAS and SATA receptacles		
Product Manager:	Ng Kok Chin		
Subject:	Notification of Change with Immediate Effectivity		
Distribution:	General		
Type of Change:	Packaging Change		
Change Description:	<p>1. To make chamfer in one corner of the tray to prevent wrong orientation. 2. Bigger slot for ease of tray separation @ auto tray loader</p> <div style="display: flex; justify-content: space-around;"> <div style="text-align: center;"> <p>Before - Radius edge</p>  </div> <div style="text-align: center;"> <p>After - Chamfer edge</p>  </div> <div style="text-align: center;"> <p>Before - Slot is optional</p>  </div> <div style="text-align: center;"> <p>After - Slot is required for automation</p>  </div> </div>		
Reason for Change:	<p>To prevent wrong orientation of tray in the packing machine and for easier tray separation at auto tray loader.</p> <p>By R.1 - Added images and details of second change happening along with addition of chamfer.</p>		
Affected Parts:	Refer to part number list		
Effective Date of Change:	November 3, 2015		
Last Time Buy Date:	NA		
Last Disty Return Date:	NA		
Last Time Shipment Date	NA		
Datasheet Attached?	NA		
Qual/Test Data Attached?	NA		
Samples Availability Date:	November	01	2015
Available Alternatives?	N/A		
Questions?	Contact your local FCI Representative, or Product Manager		
	Ng Kok Chin / Product Manager		
	+65-68606182 / ngkoc@fci.com		

Note:

Customer shall intimate the product Manager any Concern regarding the PCN within 3 weeks of the release date.
 PCN is considered approved by the customer if no communication is received within 3 weeks