

ASSMANN WSW components, Inc. 1840 W. Drake Drive, Suite 101 Tempe, AZ 85283 Toll Free 877.277.6266 www.assmann.us

Product Change Notification (PCN)

Issue Date: Modification/Revision Date: 12/12/2013 12/12/2013

USB

Change Notification: Description of changes: PCN-US-20131208-USB Change of Production Location Change of Part Number

1.The "-R" at end of part number is removed 2. Drawings listed below replace all previous drawings

Date of change and Implementation:	12/12/2013
Key Characteristics of Change:	Part Number Change
Products Affected:	A-USBS-B-R A-USBS-A-R A-USB-A-2P-R A-USB-A-LP-R AU-Y1010-R AU-Y1009-R A-USB/2-A-3P-R A-USB/2-B-SMT-TOP-R

Reason for Change:Unification of part numbersResponse:No response to this notification is required.



ASSMANN WSW components, Inc. 1840 W. Drake Drive, Suite 101 Tempe, AZ 85283 Toll Free 877.277.6266 www.assmann.us

Product Change Notification (PCN)

Issue Date: Modification/Revision Date: 12/12/2013 12/12/2013

Reference Documents / Attachments:

Document: Drawing

Previous Part Number	New Part Number	Drawing Number
A-USBS-B-R	A-USBSB	ASS_1122B_COrev05
A-USBS-A-R	A-USBSA	ASS_1122C_COrev11
A-USB-A-2P-R	A-USB-A-2P-C	ASS_1360A_COrev04
A-USB-A-LP-R	A-USB-A-LP-C	ASS_1413_COrev02
AU-Y1010-R	AU-Y1010	ASS_5927_CO_rev00
AU-Y1009-R	AU-Y1009	ASS_6064_CO_rev00
A-USB/2-A-3P-R	A-USB/2-A-3P	ASS_4355_CO_rev01
A-USB/2-B-SMT-TOP-R	A-USB/2-B-SMT-TOP	ASS_6095_CO_rev00